## INSTRUCTIONS FOR REPLACING CIRCUIT BOARD ON MODEL 760 APRILAIRE® HUMIDIFIERS (BEFORE SERIAL NO. 34457)

<u>WARNING!</u> 120 VOLTS MAY CAUSE SERIOUS INJURY FROM ELÉCTRICAL SHOCK. DISCONNECT POWER & SHUT OFF WATER SUPPLY BEFORE SERVICING.



- 1. Unplug power cord and remove outer housing from unit.
- Disassemble fan shroud and motor board and remove existing circuit board. Replace wire harness as needed.
- 3. Using template provided, mark and drill two 7/64" diameter holes into motor board.
- 4. Place new circuit board on motor board within ribs. **Important! Make sure the relay is in the upper left hand corner as shown on the wiring diagram.** Attach with the two screws furnished.
- 5. Reconnect wires to circuit board according to circuit board graphics and wiring diagram below.

## WIRING DIAGRAM

